

## The EBR-II X447 high-temperature U-10Zr metal alloy experiment


**W.J. Carmack, D.L. Porter, S.L. Hayes**

Idaho National Laboratory  
Idaho Falls, ID, United States

### Abstract

The X447 experiment was conducted in the Experimental Breeder Reactor II (EBR-II) from 1988 through 1992 as part of the Integral Fast Reactor programme's development and testing of metallic fuel. The experiment was designed to operate at high temperature (630°C to 660°C PICT), near the 2-sigma operational limit for metallic fuel in EBR-II; at these temperatures, it was expected to undergo extensive fuel-cladding chemical interaction. The high cladding temperatures also provided a cladding lifetime test resulting in creep-rupture failure data on irradiated D9 and HT9 cladding. After achieving a burn-up of 5%, the subassembly was removed from the reactor and examined non-destructively. Reconstituted as X447A, it was reinserted into EBR-II and continued irradiation to 10% burn-up, at which time it was removed from the reactor following an indication of fuel pin failure in the X447 subassembly. The primary failure mechanism expected for these fuel pins was creep-rupture, accelerated by a cladding wall thinned by fuel cladding-chemical interaction. All fuel pins were intact when the subassembly was examined at ~5% burn-up. However, at approximately 10% burn-up, two fuel pins were breached. Six HT-9 clad fuel pins from the experiment were destructively examined, which included two pins at 4.7% burn-up and four pins at 10% burn-up. Two pins examined at the 10% burn-up level both showed extensive reaction between the U-10Zr fuel alloy and the HT9 cladding. A previous, preliminary analysis of the X447 experiment considered the possibility that fuel-cladding chemical interaction was accelerated post-breach due to fuel overheating as a result of partial venting of the bond sodium [1]. As an example of the fuel behaviour exhibited by pins in the X447 subassembly, Figure 1 shows axial burn-up compared to cladding dilation for an intact (DP-04) pin at 10% burn-up. Cladding dilation is extremely pronounced at the top of the fuel column, where cladding temperatures are at their peak values; this would be the location of maximum cladding creep, and could be the location of maximum fuel-cladding chemical interaction (if not rate-limited by fission product supply). Not surprisingly, this is the location of cladding breach in the two pins that experienced failure.

This paper explores the post-irradiation examination results in detail to in an attempt to gain a clear understanding of the behaviour and performance of the X447 experiment, especially focusing on the progression of fuel-clad chemical interaction, fuel constituent redistribution and cladding strain.

**Figure 1: Comparison of cladding dilation with fuel column burn-up for X447 pin DP-04**

### Acknowledgements

The work presented in this paper is a result of the efforts of numerous scientists and technicians at the Argonne National Laboratory and its former Argonne-West site (now Idaho National Laboratory). Their efforts are acknowledged, and their contributions to the field of nuclear science and engineering are sure to be appreciated by future generations of the nuclear community.

This manuscript has been authored by a contractor of the United States government for the US Department of Energy, Office of Nuclear Energy, Science and Technology (NE), under DOE-NE Idaho Operations Office Contract No. DEAC0705ID14517. Accordingly, the US government retains a non-exclusive, royalty-free license to publish or reproduce the published form of this contribution, or allow others to do so, for US government purposes.

### Reference

- [1] Pahl, R.G., C.E. Lahm, S.L. Hayes, "Performance of HT9 Clad Metallic Fuel at High Temperature", *Journal of Nuclear Materials*, 204 (0), pp. 141-147 (1993).